



## FIRE RESISTANT TIMBER DOOR SCHEME

**Certificate number: IFCC 1296**

Certificate only valid if verified on website - [www.ifccertification.com](http://www.ifccertification.com)

This is a product certificate to certify that

**Aspex UK Ltd**

Aspex UK Ltd.,  
The Whittle Estate  
Whetstone  
Leicester LE8 6LH  
Tel: 0116 278 3506

Who fabricate the following timber fire doors and or doorsets:

**Halspan FD30, FD60, FD90 & FD120**  
**Strebord FD30 & FD60, Warmsprings FD90 & FD120**  
**Blankfort FD30 & FD60, Flamebreak FD30 & FD60**  
**Moralt FD30 & FD60, Vicaima FD30 & FD60**  
**Aspex FD30 & FD60 & FD120, Castella FD30**  
**Norma Doors FD30**

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.

Fire doors manufactured at factory references: A-AB2, A-AB4, A-AB15, A-AB16, A-ZF, R-B, R-C



Initial certification: 18 April 2017  
Reissued: 06 May 2022  
Valid to: 17 April 2027  
Issue status: 7

Ian Woodhouse  
Director of Certification



175

IFC Certification Ltd  
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

## **Certificate number: IFCC 1296**

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

<b>Doorset Description</b>	<b>Fire Rating</b>	<b>Assessment/ Test Report</b>
Halspan Optima	FD30	Chilt/A01204
Halspan Optima	FD60	Chilt/A01205
Halspan Prima	FD30	FEA/F97174
Halspan Prima	FD60	FEA/F96103
Halspan Prima/Optima Encapsulated (Starbank)	FD30	BMT/CAN/F15331
Halspan Prima/Optima Encapsulated (Starbank)	FD60	BMT/CAN/F15332
Halspan	FD90	Chilt/A05151
Halspan	FD120	BMT/CAN/F15082
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF377027
Blankfort 30/30+	FD30	Chilt/A12151
Blankfort 60/60+	FD60	Chilt/A12152
Flamebreak	FD30	FEA/F98164
Flamebreak	FD60	FEA/F02141
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke & FireSafe	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30 & FD60	PAR/14559/01
Moralt Laminesse FireSound	FD30 & FD60	PAR/12519/03
Moralt Laminesse FireSound 59mm	FD90	PAR/15143/01
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093
Warm Springs	FD60, FD90 & FD120	Chilt/A12138
Aspex	FD30	PAR/18712/01, WF422530
Aspex	FD60	PAR/18708/01, WF431237
Aspex	FD120	PAR/19602/01
Castella	FD30	16/12708-1540-5
Norma RF30	FD30	WF430277

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

**It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.**

**Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.**

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.